
Gila County Unique, Impaired, and Not Attaining Waters



The **Arizona Dept. of Environmental Quality** is the official arbiter of monitoring parameters and may include additional parameters at their discretion.

Gila County

Unique, Impaired, and Not-Attaining Waters

Surface Water	Stream Reach or Lake Number	Parameter(s) of Concern	Unique Water (Outstanding Arizona Water)	Impaired Water	Not- Attaining Water	TMDL Completed
Salt River Watershe	ed					
Christopher Creek	From headwaters to Tonto Creek AZ15060105-353	E. coli			Х	Х
Gibson Mine Tributary	From headwaters to Pinto Creek AZ15060103-887	Copper			Х	Х
Pinto Creek	From headwaters to tributary at Lat 33°19'27" Long 110°54'56" AZ15060103-018A	Copper			Х	Х
Pinto Creek	From tributary at Lat 33°19'27" Long 110°54'56" to Ripper Spring AZ15060103-018B	Copper			Х	Х
Pinto Creek	From Ripper Spring to Roosevelt Lake AZ15060103-018C	Selenium and copper		Х		Х
Tonto Creek	From headwaters to unnamed tributary at Lat 34°18'10" Long 111°04'14" AZ15060105-013A	Dissolved oxygen, nitrogen, <i>E. coli</i>		Х		Х
Tonto Creek	From unnamed tributary at Lat 34°18'10" Long 111°04'14" to Haigler Creek AZ15060105-013B	Nitrogen, E. coli		Х		Х
Verde Watershed						
East Verde River	From Ellison Creek to American Gulch AZ15060203-022B	Selenium		Х		

NOTE: ADEQ is the official arbiter of monitoring parameters and may include additional parameters at their discretion.